



State of Utah

Department of Natural Resources

ROBERT L. MORGAN
Executive Director

Division of Oil, Gas & Mining


LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

April 1, 2004

TO: Minerals File

FROM: Doug Jensen, Senior Reclamation Engineer 

SUBJECT: Site Inspection, 3-H Landscaping, Bright 1 & 2 Quarries, M/021/030, Iron County, Utah

Date of Inspection: March 22, 2004
Time of Inspection: 1:30 p.m.
Conditions: Sunny, Humid
Participants: Doug Jensen, DOGM

Purpose of Inspection:

I was in the area, stopped by to check the status of the quarries.

Getting to the site:

See my previous inspection memos.

Observations:

Work had been initiated on several new areas since my last visit to the site. Quarry D was started and it appears several hundred tons have been removed from the quarry. 3-H has upgraded the road from the south processing area by placing a cover of crushed rhyolite over the surface. Work at Quarry F has been started and a .5-mile road has been built to access the site. It appears the some initial blasting has taken place at Quarry F but none of the blasted material appears to have been removed to the processing area yet.

The sites were clean and where available soil has been placed in piles for reclamation of the areas in the future.

Pictures of the site were taken and are included in this report.

Conclusions and Recommendations:

I had no concerns about the operation and I will continue to monitor progress at the site in the future.

DJ:jb

Attach: photos

cc: Scott Holt, 3-H Landscaping

Ed Ginouves, BLM, Cedar City FO (UTU-79703)

O:\M021-Iron\M0210030-Bright1&2\Final\insp-03222004.doc




SOUTH PROCESSING AREA



SOUTH PROCESSING AREA




QUARRY D




SOUTH PROCESSING AREA



Quarry F



South Processing Area



South Processing Area Soil File
From Quarry F Access Road



Quarry F